

7050



0026

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

Page 1 of 4

NO. N 91-15-2-3

To the following Permittee or Operator:

Name Genwal Coal Company

Mine Crandall Canyon ☐ Surface ☒ Underground ☐ Other

County EMERY State UTAH Telephone 687-9813

Mailing Address P.O. Box 1201, Huntington Utah, 84528

State Permit No. ~~ACT/055~~ ACT/015/032

Ownership Category ☐ State ☒ Federal ☐ Fee ☐ Mixed

Date of inspection 10-24-91, 19__

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 1:30 ☐ a.m. ☒ p.m.

Operator Name (other than Permittee) n/a

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that cessation of mining is ☒ activity (see NOV 1063) is not ☐ expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

CERTIFIED P 074979 148

Date of service/mailing 11-7-91 Time of service/mailing 3:00 ☐ a.m. ☒ p.m.

Jay Marshall Permittee/Operator representative ENGINEER Title

Signature _____

Rick P. Summers Division of Oil, Gas & Mining representative Senior Hydrologist Title

[Signature] Signature #15 Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

notice of violation



NOTICE OF VIOLATION NO. N 91-15-2-3

Violation No. 1 of 3

Nature of violation

Conducting activities without approval from the Division. Construction of surface facilities described as new fan and shop building extension without approved amendment to MRP.

Provisions of act, regulations or permit violated

R614-300-142

R614-300-143

R614-301-526.110

Portion of operation to which notice applies

Fan site @ upper bench - east of portals,
Shop building extension - east of existing shop.

Remedial action required (including any interim steps)

- 1) cease construction progress immediately
- 2) obtain Division approval for an Amendment to MRP

3) Removal of structures & repair of area

Abatement time (including interim steps)

- 1) immediate
- 2) 4 weeks, no later than 5:00 pm on Dec. 5, 1991
- 3) 2 weeks, no later than 5:00 pm on Nov. 21, 1991



NOTICE OF VIOLATION NO. N 91-15-23

Violation No. 23 of 3

Nature of violation

Failure to comply w/ Permit condition specifically, Condition #2, Amendment #1 ACT/015/032-91B, approved 6/28/91. Requires updated map of surface facilities. Map submitted on 10/25/91 is not current or accurate.

Provisions of act, regulations or permit violated

R614-300-143.
R614-301-121.100
R614-301-521.100
R614-301-521.141
R614-301-521.150 + 151

Portion of operation to which notice applies

Permit: Plate 3-1

Remedial action required (including any interim steps)

- 1) Prepare and submit updated, current, accurate map of surface facilities to include accurate boundaries, configuration of land surface, existing facilities, legend, scale, N arrow, certification, Granddell Creek & channel, and other surface features as applicable. C.I. to be 2'.
 - 2) Verify aforementioned items w/ field survey by licensed surveyor or Professional Engineer.
- Abatement time (including interim steps)
1) + 2): 2 wks or 5:00 pm on November 21, 1991.



NOTICE OF VIOLATION NO. N91-15-2-3

Violation No. 3 of 3

Nature of violation

- Failure to maintain bypass culvert (UD-3) in a functional state. Culvert is disconnected.
- Failure to follow approved Plan.

Provisions of act, regulations or permit violated

R614-300-142
R614-300-143
R614-301-742.312
R614-301-750

Portion of operation to which notice applies

Division identified as UD-3 (culvert), further described as culvert located directly above portals.

Remedial action required (including any interim steps)

Repair and Replace culvert as needed to ensure function.

Abatement time (including interim steps)

2 weeks or 5:00 pm on November 21, 1991